

T-04001 FIGS. 1-6

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5

GROOVE WIDTH \overline{W}	CONVEYANCE QUALITY	NOTE
40 mm	Δ	DEFECTIVE CONVEYANCE DUE TO STATIC ELECTRICITY
30 mm	O	SMOOTH CONVEYANCE
20 mm	O	SMOOTH CONVEYANCE
10 mm	O	SMOOTH CONVEYANCE
5 mm	O	SMOOTH CONVEYANCE
0 mm	x	DEFECTIVE CONVEYANCE DUE TO STATIC ELECTRICITY

FIG. 6

GROOVE DEPTH t	STENCIL A	STENCIL B	NOTE
0. 0 mm	x	x	DEFECTIVE CONVEYANCE DUE TO STATIC ELECTRICITY
0. 0.5 mm	0	x	STATIC ELECTRICITY ONLY ON MASTER B
0. 1 mm	0	0	SMOOTH CONVEYANCE, NO CREASING
0. 4 mm	0	0	SMOOTH CONVEYANCE, NO CREASING
0. 5 mm	x	0	CREASING OF MASTER A
1. 0 mm	x	x	CREASING OF MASTERS A AND B